

48-Frame Motors


48-Frame Direct Replacements for ICP

45052

FEATURES

- Requires 10 MFD 370VAC Capacitor
- Direct Replacement for:

ICP	1009052
ICP	1172488
US Motors	K55HXCEM6402





**DIRECT
REPLACEMENT
FOR ICP**

45508

FEATURES

- Requires 5 MFD 370VAC Capacitor
- Includes special Molex plug
- Direct Replacement for:

Carrier	HC37GZ005A
GE	5KCP39BGZ257S
ICP	1172508



**DIRECT
REPLACEMENT
FOR ICP**

45598

FEATURES

- Requires 5 MFD 370VAC Capacitor
- Includes special Molex plug
- Direct Replacement for:

ICP	1064945
ICP	1082638
ICP	1082639
ICP	1085925
ICP	1086598
ICP	1092250



**DIRECT
REPLACEMENT
FOR ICP**

Item ID	H.P.	Voltage	RPM	Amps	Rotation	Bearing	Hertz	Motor Type
45052	1/2	115	1050	7.6	CWSE	Ball	60	PSC
45508	1/5	208/230	1050	1.5-1.4	CWLE	Ball	60	PSC
45598	1/5	208/230	1050	1.5-1.4	CWLE	Ball	60	PSC