

NEW



48-Frame Direct Replacements for Carrier



Features

- 7.5MFD/370V capacitor required

Item ID	H.P.	Volts	RPM	Amps	Rotation	Bearing	Hertz	Motor Type	Direct Replacement For
45113	1/5	115	1075	3.3	CWSE	Ball	60	PSC	Carrier HC37TQ113



Features

- 7.5MFD/370V Capacitor required

Item ID	H.P.	Volts	RPM	Amps	Rotation	Bearing	Hertz	Motor Type	Direct Replacement For
45114	1/5	115	1075	3.3	CCWLE	Ball	60	PSC	Carrier HC37AE114



Features

- 5MFD/370V Capacitor required

Item ID	H.P.	Volts	RPM	Amps	Rotation	Bearing	Hertz	Motor Type	Direct Replacement For
45117	1/3	115	1075	4.4	CCWLE	Ball	60	PSC	Carrier HC41AE117



Features

- 15MFD/370V Capacitor required

Item ID	H.P.	Volts	RPM	Amps	Rotation	Bearing	Hertz	Motor Type	Direct Replacement For
45118	3/4	115	1075	8.35	CCWLE	Ball	60	PSC	Carrier HC45AE118

48-Frame Direct Replacements for ICP



Features

- Requires 10 MFD 370VAC Capacitor
- 4 speed
- CW shaft end
- Ball bearing



Item ID	H.P.	Volts	RPM	Amps	Rotation	Bearing	Hertz	Motor Type	Direct Replacement For
45052	1/2	115	1050	7.6	CWSE	Ball	60	PSC	ICP 1009052, 1172488, US Motors K55HXCEM6402